Rear, Scott

From: Supervisor.Victoria <Supervisor.Victoria@innav.gc.ca>

Sent: Wednesday, November 20, 2019 5:10 PM

To: CBSA Operations; NCC / CCN (DFO/MPO); CCG Western Aids to Navigation / Aides à la

Navigation GCC (DFO/MPO); Payne, Stephen; Jourdenais, Marc; Carlow, Theresa; ROC1 /

COR1 (DFO/MPO); ROC1 / COR1 (DFO/MPO); Clinton. Rebeiro@tsb-bst. gc. ca (Clinton.Rebeiro@tsb-bst.gc.ca); PAC Radio Room / Salle de radio PAC (DFO/MPO); Environment Canada (ec.cnue-neec.ec@canada.ca); Glenn Budden (Glenn.Budden@tsb-bst.gc.ca); Harbour Master - Vancouver; Harbour Master- Victoria; Harbour Master- Victoria Assistant; Brady, Jeff; Victoria JRCC [DND]; Carrigan, Kevin; Mcculloch, Lisa; CCG MCTS RHQ Western / GCC SCTM bureau régional lOuest (DFO/MPO); Statham, Art; Mohan Raman (Mohan.Raman@tsb-bst.gc.ca); CCG West MSOC / COSM Ouest

GCC (DFO/MPO); Pacific Pilotage Authority (info@ppa.gc.ca); RCMP West Coast Marine Services; Ciammaichella, Rita; Stroud, Chad; Pickrell, Susan; SITCEN [TC]; TC Marine Safety - Vancouver; TC SITCEN alternate; Transportation Safety Board - Pacific; Zillur.

Rahman@tsb-bst.gc.ca (Zillur.Rahman@tsb-bst.gc.ca)

Subject: 1480-2019-MOR-VIC-OCEAN TRADER 1/9V3626 - ALLIANCE GRAIN EAST,

VANCOUVER - ALLISION - INITIAL

GENERAL DATA	\ - MARINE OCCU	RRENCE REPOR	I					
VESSEL NAME/	NAME/CALL SIGN/REG: OCEAN TRADER 1/9V3626							
JRCC INCIDENT	#:	V19-	PRIORITY:	DADCAST: -				
INCIDENT STAR	T TIME:	V19- PRIORITY: - BROADCAST: - 20/Nov/2019 1638 PST						
INCIDENT END	TIME:	Click here to e	enter a date. Click h	ere to enter te	d.			
NATURE OF INC	CIDENT:	ALLISION	***************************************	***************************************	***************************************			
PERSONS ON B	OARD:		LOSS OF LIFE:	No				
POSITION (GPS	/ GEOGRAPHIC):	<u>:</u>	HARBOUR – ALLIAN 123 04.43.2W	CE GRAIN EAST				
VESSEL PARTIC	<u>ULARS</u>	************************						
LOA:	224.94M	TYPE:	BULK CARRIER	OFFICIAL#	4003050			
MMSI:	564252000	GRT/DWT:	39738TLP/76596T	IMO:	9362217			
DESTINATION:	VANCOUVER, BC	LAST PORT:	***************************************	CARGO:				
FLAG:	SINGAPORE	OWNER/ AGENT CONTACT:	GRACE OCEAN PTE LTD	SHIP PHONE/SAT PHONE:				
ADDITIONAL VE	SSEL DETAILS:				·h			
SITUATION DET	AILS							
SITREP/RESOLU	TION:	DIRECTOR OF PACIFIC COAST PILOTS CALLED TO REPORT THAT THE OCEAN TRADER 1 COLLIDED WITH THE DOCK WHEN BERTHING AT ALLIANCE GRAIN EAST. PILOT REPORTS HULL SUSTAINED A DENT AND THE PADDING ON THE						
			AMAGED. SHIP OTH					
INTENTIONS OF	MASTER:							
ON-SCENE ASSI	STANCE:	***************************************						

POLLUTION/NAV HAZARD:	NONE REPORTED	NONE REPORTED						
WEATHER DETAILS								
VISIBILITY:	GOOD	WIND (KNOTS):	LIGHT					
SEA STATE:	CALM	TIDE/CURRENT:						
ALERT LIST (NAME AND DATE/TI	ME OF VERBAL ALERT)							
CCG–W ER DUTY OFFICER (IF POLLUTION PRESENT OR RISK OF DISCHARGE)								
TC MARINE SAFETY OFFICER (COMMERCIAL VESSEL ONLY OR LOSS OF LIFE ON ANY VESSEI	20/Nov/2019 164	9 PST						
VANCOUVER HBR MASTER (ONLY IF WITHIN OR BOUND FOR VANCOUVER HARBOUR)	20/Nov/2019 164	20/Nov/2019 1645 PST						
MCTS OFFICER:	JN 201							
MCTS WATCH SUPERVISOR:	JN	JN						
VICTORIA MARINE COMMUNICA	TIONS AND TRAFFIC SI	ERVICES						
CANADIAN COAST GUARD/GOVE			_					
<u>SUPERVISOR.VICTORIA@INNAV.GC.CA</u> /TEL: 250-363-6333 1-800-661-9202 / FAX: 250-363-6556								
Bahar as and Obeans - Réchas er Co Canaba - Canaba	93**\$							
Danaman Garza dis 3 e Dans Guard dana denna			. [®] Canadä					

Shift Supervisor - Victoria MCTS Centre

Telephone: 250-363-6333 Facsimile: 250-363-6556

Supervisor.Victoria@innav.gc.ca

Victoria Marine Communications & Traffic Services P.O. Box 6000 9860 West Saanich Road Sidney, BC, Canada, V8L 4B2

Rear, Scott

From: Supervisor.Victoria <Supervisor.Victoria@innav.gc.ca>

Sent: Wednesday, November 20, 2019 6:18 PM

To: CBSA Operations; NCC / CCN (DFO/MPO); CCG Western Aids to Navigation / Aides à la

Navigation GCC (DFO/MPO); Payne, Stephen; Jourdenais, Marc; Carlow, Theresa; ROC1 /

COR1 (DFO/MPO); ROC1 / COR1 (DFO/MPO); Clinton. Rebeiro@tsb-bst. gc. ca (Clinton.Rebeiro@tsb-bst.gc.ca); PAC Radio Room / Salle de radio PAC (DFO/MPO);

Environment Canada (ec.cnue-neec.ec@canada.ca); Glenn Budden (Glenn.Budden@tsb-bst.gc.ca); Harbour Master - Vancouver; Harbour Master- Victoria; Harbour Master-

Victoria Assistant; Brady, Jeff; Victoria JRCC [DND]; Carrigan, Kevin; Mcculloch, Lisa; CCG MCTS RHQ Western / GCC SCTM bureau régional lOuest (DFO/MPO); Statham, Art; Mohan Raman (Mohan.Raman@tsb-bst.gc.ca); CCG West MSOC / COSM Ouest

GCC (DFO/MPO); Pacific Pilotage Authority (info@ppa.gc.ca); RCMP West Coast Marine Services; Ciammaichella, Rita; Stroud, Chad; Pickrell, Susan; SITCEN [TC]; TC Marine Safety - Vancouver; TC SITCEN alternate; Transportation Safety Board - Pacific; Zillur.

Safety - Vancouver; TC SITCEN alternate; Transportation Safety Board - Pacific; Zillur. Rahman@tsb-bst.gc.ca (Zillur.Rahman@tsb-bst.gc.ca)

Cc: 'colley@colleywest.bc.ca'; 'oceantrader1@amosconnect.com'

Subject: FW: 1480-2019-MOR-VIC-OCEAN TRADER 1/9V3626 - ALLIANCE GRAIN EAST,

VANCOUVER - ALLISION - UPDATE #1

UPDATE #1 2019/11/20 18:05 PST

Please forward the following instructions to the master:

- Master to confirm there is no ingress of water through hull.
- Provide incident report including risk assessment.

Master is fully responsible for safety and safe operation of the vessel at all times and only proceeds if it is safe to do so.

All communications and rectification report to be sent to MCTS.

Regards

Israr Waheed

Senior Marine Inspector
Cargo and Examination Services

GENERAL DATA – MARINE OCCURRENCE REPORT							
VESSEL NAME/CALL SIGN/REG :	OCEAN TRADER 1/9V3626						
JRCC INCIDENT #:	V19- PRIORITY: - BROADCAST: -						
INCIDENT START TIME:	20/Nov/2019 1638 PST						
INCIDENT END TIME:	Click here to enter a date. Click here to enter text.						
NATURE OF INCIDENT:	ALLISION						
PERSONS ON BOARD:	LOSS OF LIFE: No						
POSITION (GPS / GEOGRAPHIC):	VANCOUVER HARBOUR – ALLIANCE GRAIN EAST						
	49 17.21.1N 123 04.43.2W						

VESSEL PARTIC	<u>ULARS</u>							
LOA:	224.94M	TYPE:	BULK CARRIER	OFFICIAL#	4003050			
MMSI:	564252000	GRT/DWT:	39738TLP/76596	IMO:	9362217			
DESTINATION: VANCOUVER, BC LAST PORT:		LAST PORT:		CARGO:				
FLAG:	SINGAPORE	OWNER/ AGENT CONTACT:	GRACE OCEAN PTE LTD	SHIP PHONE/SAT	Г			
ADDITIONAL VE	SSEL DETAILS:							
SITUATION DET	'AILS							
SITREP/RESOLU	TION:	DIRECTOR OF PACIFIC COAST PILOTS CALLED TO REPORT THAT THE OCEAN TRADER 1 COLLIDED WITH THE DOCK WHEN BERTHING AT ALLIANCE GRAIN EAST. PILOT REPORTS HULL SUSTAINED A DENT AND THE PADDING ON THE BERTH WAS DAMAGED. SHIP OTHERWISE IN GOOD CONDITION.						
INTENTIONS OF	MASTER:	***************************************	***************************************	***************************************				
ON-SCENE ASSIS	STANCE:							
POLLUTION/NA	**********************	NONE REPORT	NONE REPORTED					
WEATHER DETA	<u>VILS</u>	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	***************************************		· · · · · · · · · · · · · · · · · · ·			
VISIBILITY:		GOOD	WIND (KN	OTS): LIGI	HT			
SEA STATE:		CALM	TIDE/CURI	RENT:				
ALERT LIST (NA	ME AND DATE/TI	ME OF VERBAL	ALERT)					
CCG-W ER DUTY OF (IF POLLUTION PRESENT OR F								
TC MARINE SAFETY	OFFICER OR LOSS OF LIFE ON ANY VESSEL		20/Nov/2019 1649 PST					
VANCOUVER HBR N	***************************************		20/Nov/2019 1645 PST					
MCTS OFFICER:		JN	JN					
MCTS WATCH S	UPERVISOR:	JN						
VICTORIA MARINE COMMUNICATIONS AND TRAFFIC SERVICES CANADIAN COAST GUARD/GOVERNMENT OF CANADA SUPERVISOR.VICTORIA@INNAV.GC.CA /TEL: 250-363-6333 1-800-661-9202 / FAX: 250-363-6556								
2019 24 25 26 26 26 26 26 26 26 26 26 26 26 26 26	31202224				® Canadä			

Shift Supervisor - Victoria MCTS Centre

Telephone: 250-363-6333 Facsimile: 250-363-6556

Supervisor.Victoria@innav.gc.ca

Victoria Marine Communications & Traffic Services P.O. Box 6000 9860 West Saanich Road Sidney, BC, Canada, V8L 4B2

Rear, Scott

From: OCEAN TRADER 1 - MASTER < oceantrader1@amosconnect.com>

Sent: Thursday, November 21, 2019 3:52 AM

To: Supervisor. Victoria

CBSA Operations; NCC / CCN (DFO/MPO); CCG Western Aids to Navigation / Aides à la

Navigation GCC (DFO/MPO); Payne, Stephen; Jourdenais, Marc; Carlow, Theresa; ROC1 /

COR1 (DFO/MPO); ROC1 / COR1 (DFO/MPO); Clinton. Rebeiro@tsb-bst. gc. ca (Clinton.Rebeiro@tsb-bst.gc.ca); PAC Radio Room / Salle de radio PAC (DFO/MPO); Environment Canada (ec.cnue-neec.ec@canada.ca); Glenn Budden (Glenn.Budden@tsb-bst.gc.ca); Harbour Master - Vancouver; Harbour Master- Victoria; Harbour Master- Victoria Assistant; Brady, Jeff; Victoria JRCC [DND]; Carrigan, Kevin; Mcculloch, Lisa; CCG MCTS RHQ Western / GCC SCTM bureau régional IOuest (DFO/MPO); Statham, Art; Mohan Raman (Mohan.Raman@tsb-bst.gc.ca); CCG West MSOC / COSM Ouest GCC (DFO/MPO); Pacific Pilotage Authority (info@ppa.gc.ca); RCMP West Coast Marine Services; Ciammaichella, Rita; Stroud, Chad; Pickrell, Susan; SITCEN [TC]; TC Marine Safety - Vancouver; TC SITCEN alternate; Transportation Safety Board - Pacific; Zillur.

Operations New York (ULTRABULK); Norden/Bulk Operations; S.Ganesh; Synergy Group Operations; Capt. Anand Vasanthan ADPA; Niju Kurian JK Tech Supt; Synergy Oceanic

Rahman@tsb-bst. gc. ca (Zillur.Rahman@tsb-bst.gc.ca); 'colley@colleywest.bc.ca';

Insurance; Synergy Oceanic QHSE; VGOceanTrader1

Subject: Re: 1480-2019-MOR-VIC-OCEAN TRADER 1/9V3626 - ALLIANCE GRAIN EAST,

VANCOUVER - ALLISION - UPDATE #1

Attachments: RA Sailing Vessel to discharge port (China) with dent on hul.pdf; Incident Report 20 Nov

19.pdf

Importance: High

Dear Sir,

Good day.

Duly received mail, well noted. Please see the remarks that follows as per below queries.

Kindly acknowledge safe receipt.

Thank you.

Best regards, Capt. Alex F. Azares Master M/V Ocean Trader I

SMT: UTC-8

E-Mail:oceantrader1@amosconnect.com

FBB Phone:+870-773151881 (Cabin + Bridge) Sat C:456425212 MMSI :564252000

NOTE: Vessels incoming Email size is restricted to Max 1 MB File.

^{*}For urgent matters please notify via Sat-C or follow up by phone.

^{*}Ship's e-mail is not monitored continuously.

From: Supervisor. Victoria

Date: Thu, 21 Nov 2019 12:18 +1000 Msg: AMOS-1451950100

Subject: FW: 1480-2019-MOR-VIC-OCEAN TRADER 1/9V3626 - ALLIANCE GRAIN EAST, VANCOUVER - ALLISION - UPDATE

#1

To: CBSA Operations

To: Ottawa NCC-CCN [DFO]

To: CCG-W Aids to Navigation (DFO.CCG-Western-AidstoNavigation-Aides

To: CCG-W JRCC A/Supervisor

To: CCG-W Manager Marine Aids Coastal

To: CCG-W Marine Aids Coastal Officer

To: CCG-W ROC - Alerting

To: CCG-W ROC - OPERATIONS (roc1cor1@dfo-mpo.gc.ca)

To: Clinton. Rebeiro@tsb-bst.gc. ca (Clinton.Rebeiro@tsb-bst.gc.ca)

To: DFO Radio Room - Aldergrove

To: Environment Canada (ec.cnue-neec.ec@canada.ca)

To: Glenn Budden (Glenn.Budden@tsb-bst.gc.ca)

To: Harbour Master - Vancouver

To: Harbour Master-Victoria

To: Harbour Master-Victoria Assistant

To: Jeff Brady

To: Victoria JRCC [DND]

To: Kevin, Carrigan

To: Lisa McCulloch

To: MCTS Regional Office

To: MCTS-W REGIONAL SUPERINTENDANT (AS)

To: Mohan Raman (Mohan.Raman@tsb-bst.gc.ca)

To: Victoria MSOC West [DFO]

To: Pacific Pilotage Authority (info@ppa.gc.ca)

To: RCMP West Coast Marine Services

To: RITA CIAMMAICHELLA

To: Stroud, Chad

To: Sue Pickrell

To: SITCEN [TC]

To: TC Marine Safety - Vancouver

To: TC SITCEN alternate

To: Transportation Safety Board - Pacific

To: Zillur. Rahman@tsb-bst. gc. ca (Zillur.Rahman@tsb-bst.gc.ca)

Cc: 'colley@colleywest.bc.ca'

Cc: 'oceantrader1@amosconnect.com'

UPDATE #1 2019/11/20 18:05 PST

Please forward the following instructions to the master:

Master to confirm there is no ingress of water through hull.

Answer: Confirmed, no water ingress of water through hull.

Provide incident report including risk assessment.

Answer: Please see the attached.

Master is fully responsible for safety and safe operation of the vessel at all times and only proceeds if it is safe to do so.

All communications and rectification report to be sent to MCTS. Regards Israr Waheed **Senior Marine Inspector Cargo and Examination Services GENERAL DATA - MARINE OCCURRENCE REPORT** VESSEL NAME/CALL SIGN/REG: OCEAN TRADER I/9V3626 JRCC INCIDENT#: V19-PRIORITY: **BROADCAST: INCIDENT START TIME:** 20/Nov/2019 1638 PST INCIDENT END TIME: 20/Nov/2019 1612 PST (All lines made fast at AGT-East) Click here to enter a date. Click here to enter text. **NATURE OF INCIDENT: ALLISION** PERSONS ON BOARD: 21 crew including Master / 1 POB

LOSS OF LIFE:

NO

POSITION (GPS / GEOGRAPHIC): VANCOUVER HARBOUR - ALLIANCE GRAIN EAST 49 17.21.1N 123 04.43.2W

49 17.21.1N 123 04.43.2W
VESSEL PARTICULARS
LOA: 224.94M
TYPE: BULK CARRIER
OFFICIAL # 400305
MMSI: 564252000
GRT/DWT: 39738/76596T
IMO: 9362217
DESTINATION: VANCOUVER, BC
LAST PORT: FSD-4, VANCOUVEER, BC AGT-East, VANCOUVEER, BC
CARGO: CMP=35843.4850 MT 2 ROW MALT BARLEY=23,213.820 MT
FLAG: SINGAPORE
OWNER/AGENT CONTACT: GLOBAL UNITED SHIPPING (S) PTE LTD/ COLLEY WEST SHIPPING LTD +1 (604) 6873733
SHIP PHONE/SAT PHONE: +870-77315188
ADDITIONAL VESSEL DETAILS:

LOADED CONDITION.

SITUATION DETAILS SITREP/RESOLUTION: DIRECTOR OF PACIFIC COAST PILOTS CALLED TO REPORT THAT THE OCEAN TRADER 1 COLLIDED WITH THE DOCK WHEN BERTHING AT ALLIANCE GRAIN EAST. PILOT REPORTS HULL SUSTAINED A DENT AND THE PADDING ON THE BERTH WAS DAMAGED. SHIP OTHERWISE IN GOOD CONDITION. **INTENTIONS OF MASTER:** VERIFY THE EXTENT OF DAMAGE, CONTINUE MONITORING OF WBT'S AND CH-BILGES. REQUEST ASSISTANCE AND RECOMMENDATION/S FROM THE ATTENDING SURVEYOR/S. **ON-SCENE ASSISTANCE:** REPORTED TO GOOD OWNERS AND AGENTS (COLLEY WEST) FOR VERBAL REPORT. **POLLUTION/NAV HAZARD:** NONE REPORTED WEATHER DETAILS VISIBILITY: GOOD WIND (KNOTS): LIGHT **SEA STATE: CALM** TIDE/CURRENT: ALERT LIST (NAME AND DATE/TIME OF VERBAL ALERT) CCG-W ER DUTY OFFICER (IF POLLUTION PRESENT OR RISK OF DISCHARGE) TC MARINE SAFETY OFFICER (COMMERCIAL VESSEL ONLY OR LOSS OF LIFE ON ANY VESSEL)

20/Nov/2019 1649 PST

VANCOUVER HBR MASTER

(ONLY IF WITHIN OR BOUND FOR VANCOUVER HARBOUR)

20/Nov/2019 1645 PST

MCTS OFFICER:

JN

MCTS WATCH SUPERVISOR:

JN

VICTORIA MARINE COMMUNICATIONS AND TRAFFIC SERVICES

CANADIAN COAST GUARD/GOVERNMENT OF CANADA

SUPERVISOR.VICTORIA@INNAV.GC.CA<mailto:SUPERVISOR.VICTORIA@INNAV.GC.CA> /TEL: 250-363-6333 | 1-800-661-9202 / FAX: 250-363-6556

[cid:image001.png@01D35022.D7AF5AE0] [cid:image002.png@01D35022.D7AF5AE0] [cid:image003.png@01D35022.D7AF5AE0]

Shift Supervisor - Victoria MCTS Centre

Telephone: 250-363-6333 Facsimile: 250-363-6556

Supervisor.Victoria@innav.gc.ca<mailto:Supervisor.Victoria@innav.gc.ca>

Victoria Marine Communications & Traffic Services P.O. Box 6000 9860 West Saanich Road Sidney, BC, Canada, V8L 4B2

CEAN TRADE



HAZARD IDENTIFICATION AND RISK ASSESSMENT FORM

$- q_1 \cdots q_1 \cdots q_n q_n q_1 \cdots q_n q_n q_n q_n q_n q_n q_n q_n q_n q_n$	1121				
S.No (Synergy / Vessel / Year/ S.no):	SOPL / OT1 / 2019 /NOVEMBER/001				
Vessel Name / Office Name:	OCEAN TRADER I				
Location:	in Port				
Date of carrying out RA:	20-11-2019				
Expected Date and Time of activity:	20-11-2019				
Expected duration of the activity:					
Office Approval obtained	Yes				
Risk Assessment Reviewed On:	20-11-2019				
Asset Activity:	Others				
Asset Condition:	Loaded				
Risk Assessment required for:	Hazardous activity				
Nature of Work:	Sailing Vessel to discharge port (China) with dent on huli				
Area of Work	ship's stability and water integrity				
Concurrent activity affecting main activity	NIL.				
	Injury - Checklist (Contingency Manual Ch 5.17.11)				
Worst Case Scenario and (Contingency Manual Ch05: Response	Hull Breach - Checklist (Contingency Manual Ch 5.17.5)				
Measure Checklist)	Collision / Allison - Checklist (Contingency Manual Ch 5.17.4)				

Notes:

- 1. Sample Database to be referred, while performing a task, to review and amend the sample RA to a job specific RA.
- 2. Level II risk assessment to be made for new or unfamiliar tasks (not already covered in our SMS). See section 8.4.1/8.4.2
- 3. Office approval needed for Level II Risk assessment only if the residual risk remains HIGH or VERY HIGH after further risk control measures. Only work sheet 'Information Input' & Pg. 1 Table' is to be sent to office for approval.
- Job scope has to be systematically breakdown and sequentially placed in 'Activity Step' section.
- 5. Control measures that are not already included in the company procedures are to be reflected in the 'Further risk control measures'
- 6. Worst case scenario are the measures (checklist) that are given in the contingency manual that would control the risk from further escalating.

^{*}Refer to instructions page for differentiation between on RA I and RA II.

HAZARD IDENTIFICATION AND RISK ASSESSMENT FORM

	Name / Date and Signature (PtC-Ensuring the control messures are in place)	Jo Minera 20/11/2019	Rafformin 4110 Aromorea 20/11/2019	12 Jamen c/10/00/0000000000000000000000000000000	Pomen Lottel 2019
Risk	Residual Risk	Ltow	icw	LOW	LOW
Modified Risk	Consequences	SERIOUS HARM	SERIOUS HARM	SERIOUS HARM	MODERATE HARM
Ź	Likelihood	Remote	Remote	Remote	Unlikely
	Further Risk Control Measures	Regular sounding of the Compartment.	Irrspection by Class prior sailing		Monitoring vessel from Office and providing additional weather updates.
is k	Residual Risk	Medium	Medium	tsw	Medium
Existing Risk	Consequences	SERIOUS HARM	SERIOUS HARM	SERIOUS HARM	MODERATE HARM
G	Likelihood	Unlikely	Unlikely	Remote	Likely
	Recovery Messures (Messures in place to reduce the consequence if inadverent event take place; eg. Placing of fire extinguishers, stretchers, Rescue davits etc.)	Comply with Emergency Checklist for hull breach. Refer Emergency contact list, call for external assistance.	Comply with Emergency Checklist for hull breach. Refer Emergency contact list, call for external assistance.	Comply with Emergency Checklist for hull breach. Refer Emergency contact list, call for external assistance.	Comply with Emergency Checklist for hull breach. Refer Emergency contact list, call for external assistance
	Existing Control Measure (Control measures in place to prevent occuring of inadverent event due to hazard in	Dent on the Hull visually inspected and adjacent compartment sounded. Ascertained no cracks or water ingress. SF/BM within limits.	Monttoring compartment by sounding, SF/BM within limits. Weather routing.	Crew briefed, Contingency drills on hull breach planned.	Weather routing guidance followed Speed reduction and course alteration to avoid areas of heavy weather
	Consequence (Possible outcome from inadvertent event because of mention hazard)	Loss of Stability, Cargo damage	Loss of Stability, Cargo damage	Loss of Stability, Cargo damage	Loss of Stability, Cargo damage
	Hazards associated with each activity step, Hazard identification shall focus on its affect to people, environment, asset & reputation)	Water ingress during passage	Crack developing during the voyage.	Crew unprepared for Contingency	Adverse weather
	Activity Step (Job Scope break down and placed sequentially)	Sailing Vessel to discharge port (China) with dent on hull	Sailing Vessel to discharge port (China) with dent on hull	Sailing Vessel to discharge port (China) with dent on hull	Sailing Vessel to discharge port (China) with dent on hull
	. S	- 64	rN .	m	4

21 NOV- 2019

Hazard Review Date

21 MW 2019

21 NOV 2017

21 MW. 2019

Task Completed Time

Approved By

HAZARD IDENTIFICATION AND RISK ASSESSMENT WERE DISCUSSED / BRIEFED TO THE FOLLOWING CREW MEMBERS (Applicable to level 2 RA only)

Task Commencement Time Risk Assessment done by

Rank

gnature

Edition No.1 / Rev.No.0 Date: 07-Jan-2019

SF 23

INCIDENT REPORTING ACCIDENT / DAMAGE REPORT

Synergy Group

(In case of injury is reported, please use injury reporting form too.) Date of report: 20 Nov. 2019 (Eg. DEH-01/09) In case an injury also involved, please add injury report also. (Form SF-06) Ref.No. Bulk Carrier BB. Type of ship AA. Name Of Ship: Ocean Trader 1 DD. Time: CC. Date of Damage: 1550 LT Nov. 20, 2019 EE. Ship Status (At Sea / Port/ Anchorage): FF. Makeup of If port (PIs mention name) Entering (AGT East) Complement 21 Crew incl Master and 1 Pilot Vancouver, Canada GG. Related Department (Deck / Engine / Catering) : Deck HH. Narrative - Description of Events Leading to Accident: (Add additional pages if necessary) (Please mention the events chronologically) 1412 LT = Pilot Onboard, SBE 1415 LT = Master / Pilot Exchange Info. 1418 LT = Start heaving up port anchor 1436 LT = Anchor aweigh 1530 LT = Forward tug made fast ("SST SALISH") 1533 LT = Aft tug made fast ("SST CAPILANO") 1550 LT= Vessel hit the fender and damage of AGT-East, same caused dent, damage on the vessel hull in way of Hatch no. 1. 1600 LT = First line Ashore 1612 LT = All Lines made fast / Initial call to office emergency contact. 1615 LT= Forward & Aft tug cast off 1624 LT= Pilot Off 1630 LT= Initial notification, inform agent (Colley West) by telephone about the incident. Inspection of damag sounding of ballast tanks and cargo hold bilges carried out. Verify prevention of pollution. II. Any regulatory report required? Yes 🗹 No П Office Ship If yes, who will make? JJ. Possibility of recurrence (Refer HSM Ch 08) П Very Likely Very Unlikely ☐ Un Likely 1 Likely KK. Incident Category (Ref. Ch.9 Ship Management Manual) Minor Critical/Severe Harm Marginal / Moderate Harm 4 Catastrophic / Extremely harmful LL. Consequence Environmental Damage Fatality / Disability 1 Additionally send Injury Report Form SF-06) Commercial loss (loss of hire) Reputation loss / Media exposure Personal Injury Additionally send Injury Report Form SF-06) Third party damage (Other vessel, floating objects.

Original Synergy Copy: Vessel File SF-05

Page 1 of 5

Rev. No. 2

7-JUN-16

	4 HERO		INCI	DENT REPORTING	Synergy Group
8	A 2	ACC	IDEN	T / DAMAGE REPORT	
n	× ×	(In case of	injury is re	eported, please use injury reporting form too.)	
-	Own yeasel hull dar	nage	3	Shore structure & Cargo ashore or on o	other ship)
	Own vessel hull dar	ery damage		Other losses (Please specify)	1 Shore fender damaged
	Own vessel cargo d	lamage		Time delay to the vessel	
	Own vessel-other pr	operty damage		Man hour lost	

Original : Synergy Copy : Vessei File **SF-05** Page 2 of 5

Rev.No. 2 7-JUN-16



INCIDENT REPORTING ACCIDENT / DAMAGE REPORT

Synergy Group

(In case of injury is reported, please use injury reporting form too.)

MM. Cause Analysis (Write descriptively)								
Direct cause: (Unsafe act and unsafe condition that caused the accident)								
Improper execution of tugs in the confined spaces, considering weather factors- currents								
Indirect cause (write the descriptively job & personal factors that existed)								
Vessel maneuvering at confined spaces.								
Root cause: (Write Descriptively the root causes) (May address lack of planning, lack of standards, lack of compliance etc.)								
Lack of planning of execution of proper ship's handling. Failure to execute the assist of tugs due to confined								
spaces maneuverability.								
NN. Immediate Action taken. Report the initial notification of the incident on emergency contact, then advise good local agents. Verify the safety of the crew, the vessel condition and pollution prevention as necessary. Inform the office crisis management and the good local agent verbally initially through telephone.								
OO. Action taken to Prevent Recurrence: (Corrective Action) Proper planning & positioning of tugs.								
PP. Purchase Request Number (If raised) : NA								
Signature of Master Signature of Chief Engineer Name of Master: Cap Alex F zages Name of Chief Engineer Roberto A. Chong								

HEROL

INCIDENT REPORTING ACCIDENT / DAMAGE REPORT

Synergy Group

(In case of injury is reported, please use injury reporting form too.)

o,	PONE	For Statistics &	Analysi	s (Tick appropriate)				
OO. Details of Accident (tick appropriate. May be more than one)								
	Collision Fire / Explosion Grounding during Navigation			Cargo Damage due to Hatch cover leaks Cargo Damage due to movement of cargo Cargo Damage due to Contamination				
	Touching Bottom at Berth			Cargo lost Overboard				
	Contact with Shore Objects			Cargo damage due to other causes				
	Contact with Ice			Oil Pollution				
	Contact with Floating Objects	3		Pollution caused by Garbage				
	Structural Failure of Hull			Pollution due to Chemicals				
	Propulsion Failure			Pollution Resulting from Sewage				
	Steering Failure			Poilution caused by Hazardous Cargoes				
	Other Machinery Failure			Air Pollution due to Smoke				
	Mooring Failure			Power Failure				
	Explosion / Fire involving care	go		Equipment on Fire				
	Explosion -Boiler/Associated			Heavy Weather Damage				
	Personnel/ Equipment Contact	ct		Slips/Trips/Falls				
	Exposure - Harmful Substand	es		Pollution Marine / Atmospheric				
	Explosion - Others			Others (Specify)				
	Direct causes: (tick appropri	iate. May be more tha	in one)					
	Failure to follow rules and re	egulations		09. Failure to secure				
02	Failure to use ppe properly			10. Making safety devices inoperative				
03	Operating equipment or ma	chinery		11. Improper position for task				
	without authority			12. Improper lifting, handling or storage				
04	Incorrect use of equipment	or machinery		13. Horseplay/inappropriate behaviour				
05	Using defective equipment	or machinery		14. Under the influence of alcohol	_			
06	Failure to follow repair/main	tenance		and/or other drugs				
	instructions		_	15. Sabotage, wilful damage				
07	Incorrect navigation or ship	handling		16. Suicide/homicide				
08	Failure to warn			17. Other substandard act(s)				

Original . Synergy Copy . Vessei File SF-05

Page 4 of 5

Rev.No. 2 7-JUN-16



INCIDENT REPORTING ACCIDENT / DAMAGE REPORT

Synergy Group

(In case of injury is reported, please use injury reporting form too.)

For Statistics & Analysis (Tick appropriate)						
Unsafe conditions				g-1000000		
18. Inadequate guards or barrie	ers		30. Noise or temperature			
19. Inadequate or defective pp	e		31. Radiation exposure			
20. Defective equipment, mach	ninery or tools		32. Inadequate ventilation			
21. Hull or structural condition			33. Environmental conditions			
22. Inadequate warning system	n		34. Out-dated charts, publications and			
23. Adverse weather condition:	s		other documentation			
24. Adverse sea conditions			35. Bunkers and/or lubricating oils			
25. Poor housekeeping			36. Port and berthing facilities			
26. Congestion or restricted ac	ction		37. Cargo			
27. Inadequate or excess illum	ination		38. Other substandard conditions(s)			
28. Fire and explosion hazards	;		39. Workspace Restrictions			
29. Inadequate / Excessive ligh	nting					
QQ. Indirect Causes (tick appro-	priate. May be more that	n one)				
Personal factors						
01 Inadequate physical/physic	piogical capability		05. Lack of knowledge			
02. inadequate mental/psycho	logical capability		06. Lack of skill			
03. Physical or physiological st	tress		07. Improper motivation			
04. Mental or psychological str	ress					
Job Factors						
08. Inadequate leadership and	d/or supervision		12. Inadequate tools and equipment			
09 Inadequate engineering			13. Inadequate work standards			
10. Inadequate purchasing			14. Excessive wear and tear			
11 Inadequate maintenance			15. Abuse or misuse			

Rear, Scott

From: Supervisor.Victoria <Supervisor.Victoria@innav.gc.ca>

Sent: Thursday, November 21, 2019 5:46 AM

To: CBSA Operations; NCC / CCN (DFO/MPO); CCG Western Aids to Navigation / Aides à la

Navigation GCC (DFO/MPO); Payne, Stephen; Jourdenais, Marc; Carlow, Theresa; ROC1 /

COR1 (DFO/MPO); ROC1 / COR1 (DFO/MPO); Clinton. Rebeiro@tsb-bst. gc. ca (Clinton.Rebeiro@tsb-bst.gc.ca); PAC Radio Room / Salle de radio PAC (DFO/MPO); Environment Canada (ec.cnue-neec.ec@canada.ca); Glenn Budden (Glenn.Budden@tsb-bst.gc.ca); Harbour Master - Vancouver; Harbour Master- Victoria ; Harbour Master- Victoria Assistant; Brady, Jeff; Victoria JRCC [DND]; Carrigan, Kevin; Mcculloch, Lisa; CCG MCTS RHQ Western / GCC SCTM bureau régional lOuest (DFO/MPO); Statham,

Art; Mohan Raman (Mohan.Raman@tsb-bst.gc.ca); CCG West MSOC / COSM Ouest GCC (DFO/MPO); Pacific Pilotage Authority (info@ppa.gc.ca); RCMP West Coast Marine Services; Ciammaichella, Rita; Stroud, Chad; Pickrell, Susan; SITCEN [TC]; TC Marine Safety - Vancouver; TC SITCEN alternate; Transportation Safety Board - Pacific; Zillur.

Rahman@tsb-bst.gc.ca (Zillur.Rahman@tsb-bst.gc.ca)

Cc: Waheed, Israr

Subject: FW: 1480-2019-MOR-VIC-OCEAN TRADER 1/9V3626 - ALLIANCE GRAIN EAST,

VANCOUVER - ALLISION - UPDATE #2

Attachments: RA Sailing Vessel to discharge port (China) with dent on hul.pdf; Incident Report 20 Nov

19.pdf

Follow Up Flag:

Flag Status:

Follow up Completed

UPDATE #2 2019/11/21 03:52 PST

Duly received mail, well noted. Please see the remarks that follows as per below queries.

Kindly acknowledge safe receipt.

Thank you.

Best regards, Capt. Alex F. Azares Master M/V Ocean Trader I

UPDATE #1 2019/11/20 18:05 PST

Please forward the following instructions to the master:

- Master to confirm there is no ingress of water through hull.
- Provide incident report including risk assessment.

Master is fully responsible for safety and safe operation of the vessel at all times and only proceeds if it is safe to do so.

All communications and rectification report to be sent to MCTS.

Regards

Israr Waheed

Senior Marine Inspector Cargo and Examination Services

GENERAL DATA – MARINE OCCURRENCE REPORT									
VESSEL NAME/C	OCEAN TRADER 1/9V3626								
JRCC INCIDENT	V19-	V19- PRIORITY: - BROADCAST: -							
INCIDENT START	ΓTIME:	20/Nov/2019	1638 PS	ST.					
INCIDENT END T	IME:	Click here to e	nter a c	late. Click h	ere to enter t	ext.			
NATURE OF INC	IDENT:	ALLISION							
PERSONS ON BO	DARD:		LOSS OF LIFE: No						
POSITION (GPS ,	/ GEOGRAPHIC):	VANCOUVER I 49 17.21.1N			CE GRAIN EAS	Т			
VESSEL PARTICU	JLARS		•••••						
LOA:	224.94M	TYPE:	BULK	CARRIER	OFFICIAL#	4003050			
MMSI:	564252000	GRT/DWT:	39738	TLP/76596T	IMO:	9362217			
DESTINATION:	VANCOUVER, BC	LAST PORT:			CARGO:				
FLAG:	SINGAPORE	OWNER/ AGENT CONTACT:	GRACI PTE LT		SHIP PHONE/SA PHONE:	т			
ADDITIONAL VE	SSEL DETAILS:								
SITUATION DET	AILS								
SITREP/RESOLUTION:		DIRECTOR OF PACIFIC COAST PILOTS CALLED TO REPORT THAT THE OCEAN TRADER 1 COLLIDED WITH THE DOCK WHEN BERTHING AT ALLIANCE GRAIN EAST. PILOT REPORTS HULL SUSTAINED A DENT AND THE PADDING ON THE BERTH WAS DAMAGED. SHIP OTHERWISE IN GOOD CONDITION.							
INTENTIONS OF	MASTER:								
ON-SCENE ASSIS	STANCE:								
POLLUTION/NA	V HAZARD:	NONE REPORTED							
WEATHER DETA	<u>IILS</u>								
VISIBILITY:		GOOD		WIND (KNOTS): LI		HT			
SEA STATE:	CALM		TIDE/CURR	ENT:					
ALERT LIST (NAME AND DATE/TIME OF VERBAL ALERT)									
CCG-W ER DUTY OF (IF POLLUTION PRESENT OR R									
TC MARINE SAFETY OFFICER (COMMERCIAL VESSEL ONLY OR LOSS OF LIFE ON ANY VESSEL)		20/Nov/2019 1649 PST							
VANCOUVER HBR MASTER (ONLY IF WITHIN OR BOUND FOR VANCOUVER HARBOUR)		20/Nov/20	20/Nov/2019 1645 PST						
MCTS OFFICER:	JN								

MCTS WATCH SUPERVISOR:

JN

VICTORIA MARINE COMMUNICATIONS AND TRAFFIC SERVICES CANADIAN COAST GUARD/GOVERNMENT OF CANADA

SUPERVISOR.VICTORIA@INNAV.GC.CA /TEL: 250-363-6333 | 1-800-661-9202 / FAX: 250-363-6556

Fisher es and Oceans Râches et Océans Canada Canada

Canadian

Caros oblaie

Coast Guard

canadienne



Shift Supervisor - Victoria MCTS Centre

Telephone: 250-363-6333 Facsimile: 250-363-6556

Supervisor.Victoria@innav.gc.ca

Victoria Marine Communications & Traffic Services P.O. Box 6000 9860 West Saanich Road Sidney, BC, Canada, V8L 4B2

Rear, Scott

From: Supervisor.Victoria <Supervisor.Victoria@innav.gc.ca>

Sent: Thursday, November 28, 2019 2:55 PM

To: Rear, Scott

Subject: FW: 1480-2019-MOR-VIC-OCEAN TRADER 1/9V3626 - ALLIANCE GRAIN EAST,

VANCOUVER - ALLISION - UPDATE #3

Attachments: NKK Report 21 Nov 19.pdf

From: Supervisor. Victoria

Sent: Thursday, November 21, 2019 12:38 PM

To: CBSA Operations <953NPCU05G@cbsa-asfc.gc.ca>; CCG National Coordination Centre <NCC-CCN.XNCR@dfompo.gc.ca>; CCG-W Aids to Navigation (DFO.CCG-Western-AidstoNavigation-AidesalaNavigation-IOuest-GCC.MPO@dfompo.gc.ca) <DFO.CCG-Western-AidstoNavigation-AidesalaNavigation-lOuest-GCC.MPO@dfo-mpo.gc.ca>; CCG-W JRCC A/Supervisor <Stephen.payne@dfo-mpo.gc.ca>; CCG-W Manager Marine Aids Coastal <marc.jourdenais@dfompo.gc.ca>; CCG-W Marine Aids Coastal Officer <theresa.carlow@dfo-mpo.gc.ca>; CCG-W ROC - Alerting <dfo.roc1cor1.mpo@dfo-mpo.gc.ca>; CCG-W ROC - OPERATIONS (roc1cor1@dfo-mpo.gc.ca) <roc1cor1@dfo-mpo.gc.ca>; Clinton. - Rebeiro@tsb-bst. gc. ca (Clinton.Rebeiro@tsb-bst.gc.ca) <Clinton.Rebeiro@tsb-bst.gc.ca>; DFO Radio Room Aldergrove <pacradioroomrhq@pac.dfo-mpo.gc.ca>; Environment Canada (ec.cnue-neec.ec@canada.ca) <ec.cnueneec.ec@canada.ca>; Glenn Budden (Glenn.Budden@tsb-bst.gc.ca) < Glenn.Budden@tsb-bst.gc.ca>; Harbour Master -Vancouver < harbour_master@portmetrovancouver.com>; Harbour Master- Victoria < mariah.mccooey@tc.gc.ca>; Harbour Master-Victoria Assistant <zoe.polden@tc.gc.ca>; Jeff Brady <jeff.brady@dfo-mpo.gc.ca>; JRCC Victoria <jrccvictoria@sarnet.dnd.ca>; Kevin, Carrigan <kevin.carrigan@dfo-mpo.gc.ca>; Lisa McCulloch <lisa.mcculloch@dfo-</p> mpo.gc.ca>; MCTS Regional Office <mcts@dfo-mpo.gc.ca>; MCTS-W REGIONAL SUPERINTENDANT (AS) <art.Statham@dfo-mpo.gc.ca>; Mohan Raman (Mohan.Raman@tsb-bst.gc.ca) <Mohan.Raman@tsb-bst.gc.ca>; MSOC WEST <MSOC-WEST.XNAT@DFO-MPO.GC.CA>; Pacific Pilotage Authority (info@ppa.gc.ca) <info@ppa.gc.ca>; RCMP West Coast Marine Services < E WCMS RCC.PO5.EDIV1@rcmp-grc.gc.ca>; RITA CIAMMAICHELLA <Rita.Ciammaichella@dfo-mpo.gc.ca>; Stroud, Chad <Chad.Stroud@dfo-mpo.gc.ca>; Sue Pickrell <susan.pickrell@dfompo.gc.ca>; TC Marine Safety - Ottawa <sitcen@tc.gc.ca>; TC Marine Safety - Vancouver <tcmarpac@tc.gc.ca>; TC SITCEN alternate <tc.sitcenhq.centredinterventionac.tc@canada.ca>; Transportation Safety Board - Pacific <MarineNotifications.Pacific@bst-tsb.gc.ca>; Zillur. Rahman@tsb-bst.gc.ca (Zillur.Rahman@tsb-bst.gc.ca) <Zillur.Rahman@tsb-bst.gc.ca>

Subject: 1480-2019-MOR-VIC-OCEAN TRADER 1/9V3626 - ALLIANCE GRAIN EAST, VANCOUVER - ALLISION - UPDATE #3

UPDATE #3 2019/11/21 - 1205PST

Vessel provides CLASS Inspection report, attached, and receives verbal clearance for departure from TCMS Inspector. Awaiting report from TCMS. Vessel currently making preparations for departure from Vancouver to China.

Regards,

Robert Booth

Shift Supervisor - Victoria MCTS Centre

Telephone: 250-363-6333

Facsimile: 250-363-6556
Supervisor.Victoria@innav.gc.ca

Victoria Marine Communications & Traffic Services P.O. Box 6000 9860 West Saanich Road Sidney, BC, Canada, V8L 4B2

UPDATE #2 2019/11/21 03:52 PST

Duly received mail, well noted. Please see the remarks that follows as per below queries.

Kindly acknowledge safe receipt.

Thank you.

Best regards, Capt. Alex F. Azares Master M/V Ocean Trader I

UPDATE #1 2019/11/20 18:05 PST

Please forward the following instructions to the master:

- Master to confirm there is no ingress of water through hull.
- Provide incident report including risk assessment.

Master is fully responsible for safety and safe operation of the vessel at all times and only proceeds if it is safe to do so.

All communications and rectification report to be sent to MCTS.

Regards

Israr Waheed

Senior Marine Inspector
Cargo and Examination Services

GENERAL DATA – MARINE OCCURRENCE REPORT					
VESSEL NAME/CALL SIGN/REG :	OCEAN TRADER 1/9V3626				
JRCC INCIDENT # :	V19-	PRIORITY:	- BROADCAST: -		
INCIDENT START TIME:	4				
	20/Nov/2019 1638 PST				
INCIDENT END TIME:	Click here to enter a date. Click here to enter text.				
NATURE OF INCIDENT:	ALLISION				
PERSONS ON BOARD:	LOSS OF LIFE: No				
POSITION (GPS / GEOGRAPHIC):	VANCOUVER HARBOUR – ALLIANCE GRAIN EAST				
	49 17.21.1N	123 04.43.2W			
VESSEL PARTICULARS					

224.94M	TYPE:	BULK C	CARRIER	OFFICIAL#	4003050	
564252000	GRT/DWT:	397387	TLP/76596T	IMO:	9362217	
VANCOUVER, BC	LAST PORT:	•		CARGO:		
SINGAPORE	OWNER/ AGENT CONTACT:	:		SHIP PHONE/S. PHONE:	AT .	
ADDITIONAL VESSEL DETAILS:						
SITUATION DETAILS						
ΓΙΟΝ:	DIRECTOR OF PACIFIC COAST PILOTS CALLED TO REPORT THAT THE OCE TRADER 1 COLLIDED WITH THE DOCK WHEN BERTHING AT ALLIANCE GRAIN EAST. PILOT REPORTS HULL SUSTAINED A DENT AND THE PADDING ON THE BERTH WAS DAMAGED. SHIP OTHERWISE IN GOOD CONDITION.				ERTHING AT ALLIANCE THE PADDING ON THE	
MASTER:		***************************************	•			
TANCE:						
√ HAZARD:	NONE REPORT	ED				
<u>ILS</u>						
	GOOD		WIND (KNOTS): LIG		GHT	
	CALM		TIDE/CURR	ENT:		
ME AND DATE/TI	ME OF VERBAL	ALERT)				
CCG-W ER DUTY OFFICER (IF POLLUTION PRESENT OR RISK OF DISCHARGE)						
	20/Nov/2019 1649 PST					
1ASTER	20/Nov/2019 1645 PST					
	JN					
MCTS WATCH SUPERVISOR: JN						
VICTORIA MARINE COMMUNICATIONS AND TRAFFIC SERVICES CANADIAN COAST GUARD/GOVERNMENT OF CANADA <u>SUPERVISOR.VICTORIA@INNAV.GC.CA</u> /TEL: 250-363-6333 1-800-661-9202 / FAX: 250-363-6556						
Jran illina					\$ Canadä	
	SAL DETAILS: AILS TION: MASTER: STANCE: V HAZARD: AILS ME AND DATE/TII FICER MISK OF DISCHARGE) OFFICER OR LOSS OF LIFE ON ANY VESSEL MASTER FOR VANCOUVER HARBOUR) UPERVISOR: LINE COMMUNICAL ST GUARD/GOVE CTORIA@INNAV.	VANCOUVER, BC LAST PORT: SINGAPORE OWNER/ AGENT CONTACT: SSEL DETAILS: AILS TION: DIRECTOR OF TRADER 1 COL GRAIN EAST. PILOT REPORT BERTH WAS D MASTER: TANCE: V HAZARD: NONE REPORT VILS GOOD CALM ME AND DATE/TIME OF VERBAL FICER SISK OF DISCHARGE) OFFICER OR LOSS OF LIFE ON ANY VESSEL) MASTER: OFFICER OR VANCOUVER HARBOUR) JN UPERVISOR: JN UPERV	VANCOUVER, BC LAST PORT: SINGAPORE OWNER/ AGENT CONTACT: SINGAPORE OWNER/ AGENT CONTACT: PTE LT SSEL DETAILS: AILS TION: DIRECTOR OF PACIFIC TRADER 1 COLLIDED V GRAIN EAST. PILOT REPORTS HULL BERTH WAS DAMAGE MASTER: V HAZARD: NONE REPORTED ILS GOOD CALM ME AND DATE/TIME OF VERBAL ALERT) FICER ISK OF DISCHARGE) OFFICER OR LOSS OF LIFE ON ANY VESSEL) AASTER FOR VANCOUVER HARBOUR) JN UPERVISOR: JN UPERVISOR: JN UPERVISOR: JN IN COMMUNICATIONS AND TRAFFIC SE ST GUARD/GOVERNMENT OF CANADA CTORIA@INNAV.GC.CA /TEL: 250-363-63	VANCOUVER, BC LAST PORT: SINGAPORE OWNER/ AGENT GRACE OCEAN PTE LTD SSEL DETAILS: AILS TION: DIRECTOR OF PACIFIC COAST PILO TRADER 1 COLLIDED WITH THE DOGRAIN EAST. PILOT REPORTS HULL SUSTAINED BERTH WAS DAMAGED. SHIP OTHER BERTH WAS DAMAGED.	SALDER OF PACIFIC COAST PILOTS CALLED T TRADER 1 COLLIDED WITH THE DOCK WHEN B GRAIN EAST. PILOT REPORTS HULL SUSTAINED A DENT AND BERTH WAS DAMAGED. SHIP OTHERWISE IN GRAND ATTEMPT. TOALED TO TIDE/CURRENT: TOALED TO TIDE/CURRENT: TOALED TO TIDE/CURRENT: TOALED T	

Shift Supervisor - Victoria MCTS Centre

Telephone: 250-363-6333 Facsimile: 250-363-6556

Supervisor.Victoria@innav.gc.ca

Victoria Marine Communications & Traffic Services

P.O. Box 6000

9860 West Saanich Road Sidney, BC, Canada, V8L 4B2

Rear, Scott

From:

Supervisor.Victoria <Supervisor.Victoria@innav.gc.ca>

Sent:

Thursday, November 28, 2019 2:56 PM

To:

Rear, Scott

Subject:

FW: 1480-2019-MOR-VIC-OCEAN TRADER 1/9V3626 - ALLIANCE GRAIN EAST,

VANCOUVER - ALLISION - FINAL

From: Supervisor. Victoria

Sent: Thursday, November 21, 2019 12:43 PM

To: CBSA Operations <953NPCU05G@cbsa-asfc.gc.ca>; CCG National Coordination Centre <NCC-CCN.XNCR@dfompo.gc.ca>; CCG-W Aids to Navigation (DFO.CCG-Western-AidstoNavigation-AidesalaNavigation-lOuest-GCC.MPO@dfompo.gc.ca) <DFO.CCG-Western-AidstoNavigation-AidesalaNavigation-lOuest-GCC.MPO@dfo-mpo.gc.ca>; CCG-W JRCC A/Supervisor <Stephen.payne@dfo-mpo.gc.ca>; CCG-W Manager Marine Aids Coastal <marc.jourdenais@dfompo.gc.ca>; CCG-W Marine Aids Coastal Officer <theresa.carlow@dfo-mpo.gc.ca>; CCG-W ROC - Alerting <dfo.roc1cor1.mpo@dfo-mpo.gc.ca>; CCG-W ROC - OPERATIONS (roc1cor1@dfo-mpo.gc.ca) <roc1cor1@dfo-mpo.gc.ca>; Clinton. Rebeiro@tsb-bst.gc.ca (Clinton.Rebeiro@tsb-bst.gc.ca) < Clinton.Rebeiro@tsb-bst.gc.ca >; DFO Radio Room -Aldergrove <pacradioroomrhq@pac.dfo-mpo.gc.ca>; Environment Canada (ec.cnue-neec.ec@canada.ca) <ec.cnueneec.ec@canada.ca>; Glenn Budden (Glenn.Budden@tsb-bst.gc.ca) < Glenn.Budden@tsb-bst.gc.ca>; Harbour Master -Vancouver <harbour_master@portmetrovancouver.com>; Harbour Master- Victoria <mariah.mccooey@tc.gc.ca>; Harbour Master-Victoria Assistant <zoe.polden@tc.gc.ca>; Jeff Brady <jeff.brady@dfo-mpo.gc.ca>; JRCC Victoria <jrccvictoria@sarnet.dnd.ca>; Kevin, Carrigan <kevin.carrigan@dfo-mpo.gc.ca>; Lisa McCulloch <lisa.mcculloch@dfo-</p> mpo.gc.ca>; MCTS Regional Office <mcts@dfo-mpo.gc.ca>; MCTS-W REGIONAL SUPERINTENDANT (AS) ; Mohan Raman (Mohan.Raman@tsb-bst.gc.ca) <Mohan.Raman@tsb-bst.gc.ca>; MSOC WEST <MSOC-WEST.XNAT@DFO-MPO.GC.CA>; Pacific Pilotage Authority (info@ppa.gc.ca) <info@ppa.gc.ca>; RCMP West Coast Marine Services <E_WCMS_RCC.PO5.EDIV1@rcmp-grc.gc.ca>; RITA CIAMMAICHELLA <Rita.Ciammaichella@dfo-mpo.gc.ca>; Stroud, Chad <Chad.Stroud@dfo-mpo.gc.ca>; Sue Pickrell <susan.pickrell@dfompo.gc.ca>; TC Marine Safety - Ottawa <sitcen@tc.gc.ca>; TC Marine Safety - Vancouver <tcmarpac@tc.gc.ca>; TC SITCEN alternate <tc.sitcenhq.centredinterventionac.tc@canada.ca>; Transportation Safety Board - Pacific <MarineNotifications.Pacific@bst-tsb.gc.ca>; Zillur. Rahman@tsb-bst.gc. ca (Zillur.Rahman@tsb-bst.gc.ca) <Zillur.Rahman@tsb-bst.gc.ca>

Subject: 1480-2019-MOR-VIC-OCEAN TRADER 1/9V3626 - ALLIANCE GRAIN EAST, VANCOUVER - ALLISION - FINAL

FINAL UPDATE 2019/11/21 - 1240PST

Please see the final report from TCMS, attached immediately below.

----Original Message-----

From: Ionescu, Ion [mailto:ion.ionescu@tc.gc.ca] Sent: Thursday, November 21, 2019 12:31 PM

To: Supervisor.Victoria <Supervisor.Victoria@innav.gc.ca>; Supervisor.Rupert <Supervisor.Rupert@innav.gc.ca>

Cc: Wilson, John < John. Wilson@tc.gc.ca>; Rushwan, Al < al.rushwan@tc.gc.ca>; Waheed, Israr

<israr.waheed@tc.gc.ca>; Sitcen HQ / Centre d'intervention AC (TC) <TC.SitcenHQ-

CentredinterventionAC.TC@tc.gc.ca>; colley@colleywest.bc.ca; 'oceantrader1@amosconnect.com'

<oceantrader1@amosconnect.com>

Subject: FW: 1480-2019-MOR-VIC-OCEAN TRADER 1/9V3626 - ALLIANCE GRAIN EAST, VANCOUVER - ALLISION -

UPDATE #2
Importance: High

Transport Canada Marine Safety Inspector Ion Ionescu gives the following Instructions:

The Class Report has been received and reviewed. No further restrictions. The vessel is cleared to sail.

The Master is fully responsible for the safety of the vessel and should only proceed if the Master considers it is safe to do so.

All communications and rectification reports to be sent to MCTS.

Capt. ION IONESCU

Senior Marine Inspector, Compliance & Enforcement and Cargo Services Transport Canada / Government of Canada ion.ionescu@tc.gc.ca / Tel: 604-666-4200 / TTY: 1-888-675-6863

Inspecteur Maritime Principal, Conformité & application des règlements et services de marchandises Transports Canada / Gouvernement du Canada ion.ionescu@tc.gc.ca / Tél: 604-666-4200 / ATS: 1-888-675-6863

Regards,

Robert Booth

Shift Supervisor - Victoria MCTS Centre

Telephone: 250-363-6333 Facsimile: 250-363-6556

Supervisor.Victoria@innav.gc.ca

Victoria Marine Communications & Traffic Services P.O. Box 6000 9860 West Saanich Road Sidney, BC, Canada, V8L 4B2

UPDATE #3 2019/11/21 - 1205PST

Vessel provides CLASS Inspection report, attached, and receives verbal clearance for departure from TCMS Inspector. Awaiting report from TCMS. Vessel currently making preparations for departure from Vancouver to China.

UPDATE #2 2019/11/21 03:52 PST

Duly received mail, well noted. Please see the remarks that follows as per below queries.

Kindly acknowledge safe receipt.

Thank you.

Best regards, Capt. Alex F. Azares Master M/V Ocean Trader I

UPDATE #1 2019/11/20 18:05 PST

Please forward the following instructions to the master:

- Master to confirm there is no ingress of water through hull.
- Provide incident report including risk assessment.

Master is fully responsible for safety and safe operation of the vessel at all times and only proceeds if it is safe to do so.

All communications and rectification report to be sent to MCTS.

Regards

Israr Waheed

Senior Marine Inspector Cargo and Examination Services

GENERAL DATA - MARINE OCCURRENCE REPORT							
VESSEL NAME/O	CALL SIGN/REG :	OCEAN TRADER 1/9V3626					
JRCC INCIDENT	#:	V19-	PRIORITY:	- BR(OADCAST: -		
INCIDENT STAR	T TIME:	20/Nov/2019 1638 PST					
INCIDENT END	ΓΙΜΕ:	Click here to enter a date. Click here to enter text.					
NATURE OF INC	IDENT:	ALLISION			***************************************		
PERSONS ON BO	OARD:	LOSS OF LIFE: No					
POSITION (GPS	/ GEOGRAPHIC):	VANCOUVER HARBOUR – ALLIANCE GRAIN EAST 49 17.21.1N 123 04.43.2W					
VESSEL PARTIC	<u>ULARS</u>						
		TYPE:	BULK CARRIER	OFFICIAL#	4003050		
MMSI:	564252000	GRT/DWT:	39738TLP/76596T	IMO:	9362217		
DESTINATION:	VANCOUVER, BC	LAST PORT:		CARGO:			
FLAG:	SINGAPORE	OWNER/ AGENT CONTACT:	GRACE OCEAN PTE LTD	SHIP PHONE/SAT PHONE:			
ADDITIONAL VE	ADDITIONAL VESSEL DETAILS:						
SITUATION DET	'AILS						
SITREP/RESOLUTION:		DIRECTOR OF PACIFIC COAST PILOTS CALLED TO REPORT THAT THE OCEAN TRADER 1 COLLIDED WITH THE DOCK WHEN BERTHING AT ALLIANCE GRAIN EAST.					

		PILOT REPORTS HULL SUSTAINED A DENT AND THE PADDING ON THE BERTH WAS DAMAGED. SHIP OTHERWISE IN GOOD CONDITION.					
INTENTIONS OF MASTER:							
ON-SCENE ASSISTANCE:							
POLLUTION/NAV HAZARD:	N	NONE REPORTED					
WEATHER DETAILS	<u>WEATHER DETAILS</u>						
VISIBILITY:	G	OOD	WIND (KNOTS):	LIGHT			
SEA STATE:	C.	ALM	TIDE/CURRENT:				
ALERT LIST (NAME AND DATE	/TIME	OF VERBAL ALERT)					
CCG-W ER DUTY OFFICER (IF POLLUTION PRESENT OR RISK OF DISCHARGE)							
TC MARINE SAFETY OFFICER (COMMERCIAL VESSEL ONLY OR LOSS OF LIFE ON ANY)	/ESSEL)	20/Nov/2019 1649 PST					
VANCOUVER HBR MASTER (ONLY IF WITHIN OR BOUND FOR VANCOUVER HARBOI	JR)	20/Nov/2019 1645 PST					
MCTS OFFICER: JN							
MCTS WATCH SUPERVISOR: JN							
VICTORIA MARINE COMMUNICATIONS AND TRAFFIC SERVICES CANADIAN COAST GUARD/GOVERNMENT OF CANADA <u>SUPERVISOR.VICTORIA@INNAV.GC.CA</u> /TEL: 250-363-6333 1-800-661-9202 / FAX: 250-363-6556							
Estar as and Oceans Páchas a Canada Canada	a. Ozaana						
Ganamar Garza di Gasar Guara ganador				® Canada			

Shift Supervisor - Victoria MCTS Centre

Telephone: 250-363-6333 Facsimile: 250-363-6556

Supervisor.Victoria@innav.gc.ca

Victoria Marine Communications & Traffic Services P.O. Box 6000 9860 West Saanich Road Sidney, BC, Canada, V8L 4B2